☐ Initial Inspection	Re-Inspection/Follow-Up	NRD:	North Platte	_ IIS#	72636	_

INITIAL	INSPECTION	OF ANIMAL	FEEDING	OPERATION
TIVI I I I I	MOLECTION	OL WITHING	recome	OFFICIALION

Name of Opera	tion				County	Morrill	_	
Address		c	ity	Zip_		_		
Phone: (	)		Phone: (_	)		Phone: (_		
Ourser/Authori	Business				ome oil.			mobile, fax, etc.)
Owner/Authori	zea кер			Em	ail:	T. Garage	7.3	-
Contact Person				C	ontact's Phone	e #: _	-	
AFO <u>currently</u> i	is: Pr	oposed 🛚	Existing Al	ND is 🗵	Large M	edium 🗌 Sr	mall	
AFO proposing	to: Bu	uild LWCF/AF	О Ехр	and/Remode	el Existing LWO	CF Othe	er: (See Remar	ks)
	AND would	d be: La	rge Med	lium Sma	III No Cha	nge in Size		
Legal Descript	ion(s):		NE	8	21	N	51	W
		1/4	1/4	Section	Townsh	nip N	Range	E or W
	-	1/4	1/4	Section	Townsh		Range	E or W
GPS READING:	Latitude		41.81583		Longitude		- 103.254	89
(NOTE: Latitud	de and longitud	e should be for	the main entro	ance to the anim	nal feeding opera	ation from the p	oublic road.)	
INVESTOCK.	Feeder	Dairy	Swine	Weaned	Poultry	Poultry	Cow-Calf	Other
LIVESTOCK:	Cattle	Cattle	>55 lbs.	Pigs	(Chickens)	(Turkeys)	Pairs	(Specify)
Existing	2000							
Proposed	N/A							
TYPE OF AFO:	Confi	ned 🛛 Ope	en Lot	Confin	ed and Open	Lot		
If open lot:	Feedlot Acre	es: ~ 12	Cont	ributing Acre	es: 0	Slope of Pe	ens:	
EXISTING Ope	eration Stat	us:	Permitted	(Permit Types:				<b>Exempt</b>
			Condition	ally Exemp	Nor	n-AFO		
EXISTING LWG	rez Mves	□No If yes	numbers &	types: 1	Racin			
						- taut luulaati	on Conal	
Name of Near	rest Surrace	water:	Tristate Ca	inai iyi	e: <u>Intermit</u>	tent irrigati	on Canai	
Distance from AFO:25 miles Drainage Description:Cropland								
Name of Primary Stream: Red Willow Creek Distance from AFO: 1.5 – 2 miles								
Static Water Level: (in feet) ~ 19 FT GWM Currently Required?								
								xempt
REMARKS: T	A STATE OF THE STA							
has one basin runoff is left in							ATT TAX TO STATE	
area next to H	100							The second second second second
miles to a dra								
into a lateral b	oranch of th	e Tristate li	rigation Ca	anal.				

Date of Inspection: 7/17/2019 Primary Inspector: Kaitlyn Steinwart & Cay Ewoldt

ADDITIONAL REMARKS: Inspection photos and site map below.

## A

## **DRAWINGS OF SITE:**



Map #1 IIS: 72636 Date Modified: 8/7/2019 Kaitlyn Steinwart Google Earth Satellite Image The red arrows indicate the path of runoff. The red circle indicates the area where runoff ponds at the base of the pens.



Photo #1 IIS: 72636 Date: 7/17/2019 Kaitlyn Steinwart Samsung Galaxy S7
This photo looks south over a portion of the basin.



Photo #2 IIS: 72636 Date: 7/17/2019 Kaitlyn Steinwart Samsung Galaxy S7
This photo looks north over a portion of the basin.



Photo #3 IIS: 72636 Date: 7/17/2019 Kaitlyn Steinwart Samsung Galaxy S7
This photo was taken facing west and overlooks the base of the northernmost pens. Highway 62 can be seen in the upper right-hand side of the photo.



Photo #4 IIS: 72636 Date: 7/17/2019 Kaitlyn Steinwart Samsung Galaxy S7
This photo was taken facing southeast and overlooks the drainage path from the base of the pens to the field, before it turns south.



36 Date: 7/17/2019 Kaitlyn Steinwart This photo overlooks the culvert under Highway 62. IIS: 72636 Samsung Galaxy S7



Photo #6 IIS: 72636 Date: 7/17/2019 Kaitlyn Steinwart Samsung Galaxy S7
This photo was taken facing south and overlooks the drainage path through the field and into the irrigation canal.




Photo #7 IIS: 72636 Date: 4/23/2019 Kaitlyn Steinwart Samsung Galaxy S7 This photo overlooks the same area shown in Photo #6, but was taken when the drainage was more visible.



## Inspection Exit Summary

NDEQ ID: NDEQ Program	n ID: 72/03/0	NDEQ Notification #:	
Facility/Operation Name:			
Address		11	
City/Town:	, County N	M Nebraska	a.
Owner/Occupant/Operator Inspection			
Inspector	Phone No E-	Mail address	
ation ternwart =	18704293	action Stemart	@nebraska.gov
, , , , , , , , , , , , , , , , , , ,		. /	@nebraska.gov
Mailing Address: Department of Envir	ronmental Quality, PO	Box 98922, Lincoln, Nebras	ka 68509-8922
Inspection Date: 7.17,	19 Start Time	e:1:00 End Time:_	1:50
No concerns observed	\ /	agency discussion needed	
Concerns observed:	A. anunci	agonoy aboassion necaca	
_ Concerns observed.			
- Woter at Int	tom of Dev	K MOXT to HUN	20 must
Vie Contained	7 , , ,	to the may	ow must
- Contraines			
- DAMESCO du	wance head	must	
	Any Tuna	WHI	
Actions to be performed immediate	ely or as soon as reas	onably practical:	
-			
Please notify the Inspector	when the above action	ons are completed.	
The Department will provide a final ins	pection report to you	usually within 45 days of the	inspection. The final inspection
report will contain a complete list of an	y alleged violations. T	his inspection exit summary	does not preclude any other lega
action by the Nebraska Department of			
oe considered in assessment of your v			
with:			ny questions concerning this
inspection exit summary.	, rease collia	a the hispector if you have a	ny questions concerning this
. A			
Vin Co II		abi	lity by the facility.
Millian Stevent			
Inspector Signature	Inspectio	n Contact Signature	revised 12/11/15